

SAPC-10744
Copy 5 of 6

30 November 1956

25X1A

MEMORANDUM FOR: [REDACTED]

SUBJECT : Performance of B Configuration

1. I found your memorandum of 16 November on the above subject (SAPC-10728) interesting. I wonder if you could do a similar analysis covering only recent B camera missions. I am interested in some appraisal of the degree of reliability that has now been achieved.
2. In this connection, have you formed any judgment as to the part played as to improper spooling of film or insufficiently rigid spools in giving rise to malfunctions of the B camera?
3. We are in the process of making decisions as to the number of B cameras required and the extent of our proper utilization of B. Accordingly, the above information is needed fairly soon.

g
RICHARD M. BISSELL, JR.
Project Director

RMB:gjg (29 Nov 56)

Distribution:

- Copy 1- [REDACTED]
2-Contracting Offr
3-Dep Proj Dir
4-Dir of Ops
✓ 5-Proj Dir Chrono
6-Project Chrono

25X1A